Work Order ID 71785 Page 1 Tuesday, July 12, 2011 9:15:34 AM D3199-3 Item ID: Setup Start **Revision ID:** Stop Item Name: Bracket, Fwd LH **Start Date:** 7/12/2011 Start Qty: 1.00 **Cust Item ID:** Required Date: 7/18/2011 Req'd Qty: 1.00 **Customer:** Reference: Start Run **Approvals: Process Plan:** Date:// **Tooling:** Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Work Center ID Description Qty **Run Hours** Code Qty Number Stamp Revision Nbr Draw Nbr D3199 D OVR 100 0.00 FLOW WATER JET B11-7-12 Waterjet 0.00 Memo FLOW CNC Waterjet Cut as per Dwg D3199 Dwg Rev: DS2 304.046 Deburr if required

0.00

0.00

1311-7-12

110

QC

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Memo

								•			
W/O:			W	ORK ORDER CHANG	ES				•		
DATE	STEP	PRO	OCEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					-						
								·			
Part No: PAR #:			Fault Cate	egory:	_ NCR: Yes	No DQ	NA: Date:				
		esolution:									
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCI	٦)					
DATE	STEP Description of NC		Corrective Action Section B			Verific	cation	Approval	Approval		
DAIL	SIEF	Section A	Initial Chief Eng	Initial Action Description Chief Eng Chief Eng			ion C	Chief Eng	QC Inspector		
								i			
,											

Work Orde			•				A				•	Page 2
Item ID: Revision ID: Item Name:	D3199-3 Bracket, Fwd	LH		Accept			i ili ili		Setup	Start Stop		
Start Date: Required Date: Reference:	7/12/2011 7/18/2011	Start Qty: 1.00 Req'd Qty: 1.00	1 1 1 1 1 1 1 1 1 1 		Cust Item I Customer:	D:						
Approvals:		nn:			. ,,,,,,	ate:			Run	Start Stop		
Sequence ID/ Work Center II 120 QC Quality Control)	Operation Description QC8- Inspect parts - seco	nd check ⁻		Tool ID nector To Dry only norly	Tool#	Plan Code	Accep Qty	t Rej Qty		Reject Number	Insp. Stamp
130 Brake NC Brake NC		Bend as per dwg Small Fab Memo		0.00	11/07/13			2)			
QC Quality Control		QC5- Inspect part comple	eteness to step on W/O	0.00 - (nspe	2 orly 17/13 00 17/13 00							

	Page											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			· .			,-						
Part No	•	PAR #:	Fault Ca	itegory:	N	CR: Yes	No DQ	A:	Date: _	· .		
Resolution:			Disposition: QA: N/C Closed:						Date: _			
NCR:		V	ORK OR	DER NON-CO	NFORMANO	E (NCR)					
DATE	STEP	Description of NC Corrective Action				Verif			Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Des	scription _{Eng}	Sign & Date	Secti	on C	Chief Eng	QC Inspector		
				:								
·		,										
								•				
										·		
		,										
				·								

0.00

0.00

Memo

Memo

Identify as per dwg & Stock Location:

Quality Control

170

Packaging

Packaging

Page 3

Insp.

Stamp

W/O:		WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
· ·										
					<u> </u>		:			
Part No	:	PAR #:	Fault Cate	Fault Category: NCR: Yes No DQA:						
Resolution:			Dispositio	on:	QA: N/C CI	osed:		Date: _		
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC		Corrective Action Section		Verific	ation	Approval	Approval	
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date			Chief Eng	QC Inspector	
									:	
	:									
				W 10-1-1						
			·							
NOTE D	1	<u> </u>			<u>.</u>				1	

Work Order ID 71785

Tuesday, July 12, 2011 9:15:34 AM



Page 4

Item ID:

D3199-3

Accept

Setup Start

Stop



Revision ID:

Item Name:

Start Date:

Bracket, Fwd LH

7/12/2011

QC:

Start Qty: 1.00

Required Date: 7/18/2011

Req'd Qty: 1.00



Date:

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Tool # Plan

Code

Date:

Stop

Reject

Qty

Sequence ID/ **Work Center ID**

180

Quality Control

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ Run Hours

0.00

SPC (Y/N):

0.00

Run

Start

Insp.

Stamp

Reject

Number

POSITIVE RECALL

Accept

Qty

Memo

W/O:			W	ORK ORDER CHANG	ES							
DATE	STEP	PRO	OCEDURE CH	ANGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Cat	egory:	_ NCR:	Yes N	lo DQ	A:	_ Date: _			
Res		esolution:	Dispositi	on:	_ QA: N	C Clo	sed:		Date: _			
NCR:			WORK ORD	DER NON-CONFORMA	ANCE (I	NCR)						
DATE	STEP	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval		
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Secti		Chief Eng	QC Inspector		
								*				
									:			
								•				
								-				
			,									

Tuesday, July 12, 2011 9:15:44 AM

Work Order ID: 71785

Parent Item:

D3199-3

Parent Item Name: Bracket, Fwd LH



Start Date: 7/12/2011

Required Date: 7/18/2011

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: RevC-prelim DD verified by:EC 11.03.31 as per ecn 11-531 DD verf:EC

IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA	Pilli	Purchased	No		100	sf	115.0630	0.1673	0.176105	, 5		
									iR	11-7-1	\supset	


304/316 .040 Sheet

Location	Loc Oty	Loc Code		
MAT020	115.063			_
116623	0.2		(-	
117550	9.363			2)
117933	105.5		117933	


Dail Ac	·ospace	Liu				•				, ,		
W/O:			WORK ORDER CHANGES									
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								<u> </u>				
	<u> </u>											
Part No):	PAR #:	Fault Category: NCR: Yes					: Yes No DQA: Date:				
Resolution		esolution:	Disposition	n:	QA:	: N/C Clo	sed:		Date: _			
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC	Corrective Action			0:	Verific	ation	Approval	Approval		
	JIL!	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector		
-				•								
												
1	1	I	1 1			ı	t		1	I		

ART AEROSI	PACE LTD			1	Nork Order:	71785
escription:		HJ QU			Part Number:	D3199-3
nspection Dwg.	3199-3 , Rev: D	εί				Page 1 of 1
	١.	ARTICLE IN	SDECTIO	NCHE	CKLIST	
	X	First Artic		7		<u> </u>
Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
	1/ 010	(619	4		V BOZ	
	4- 010	793	&		V	
	OC - 1/2	دععى	D	,	V	
	4/ 010	2.746	1		V	
4030	4010	4.030	8		V	
8.030	* .ob	8.634	7		V	
2.90	4 .30	7.9045	7		V	
3,14	4 2	3,639	7		V	
UHU,	th. 010	, ७३७	7	1	V	
4.02	1/~ =030	4,074	7		V	•
	·					
						1
	-					
						!
				1		


Measured by: 13	Audited by:	Prototype Approval:
Date: 11-7-12	Date: uloslis	Date:
Rev Date Change	to PEZ Dayorly	Revised by Approved
A New issue		KJ/JLM



	Page							•,	. .		
W/O:		i	W	ORK ORDER CHANGES	· · · · · · · · · · · · · · · · · · ·				•		
DATE	STEP	PROCI	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	PAR #: Fault Category:				A:	Date: _	te:		
		esolution:	Dispositi	ion:	A: N/C CI	osed:		Date:			
NCR:		W	ORK ORI	DER NON-CONFORMANO	CE (NCR)					
DATE	STEP	Description of NC	,	0:	Verific	ation	Approval	Approval			
	J. 2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector		
				•							
		•									
				· · · · · · · · · · · · · · · · · · ·	,						
ı	1	1	1		1			1			



	Johnace							Ą.				
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
-												
	<u> </u>											
		·										
Part No: PAR #:			Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _				
	R	esolution:	Disposition	n:	QA: N/C CI	osed:		Date: _				
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)		A. v rahitur				
DATE	STEP	Description of NC	1 242 - 6	Corrective Action Section		Verific		Approval	Approval			
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector			
		·										



W/O:		WORK ORDER CHANGES							
DATE	STEP	PRO	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				\					
			· · · · · · · · · · · · · · · · · · ·			·			
		•							
Part No		PAR #:	Fault Cat	tegory:	NCR: Yes	ICR: Yes No DQA: Date:			
	R	esolution:	Disposit	ion:	QA: N/C CI	osed:	Date: _	Date:	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC Section A	Corrective Action Section			Verification		Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector	
	-						,		
						·			
				,					

